

HS-5 Installation and Cable Package:

- (1) 5' 50635 Cable, One End with Sockets 61117-1 and (1) 1-480303-0 Connector Installed.
- (4) Pins 61118-1 and (1) 1-480305-0 Connector in Small Bag for Field Installation.
- (1) Installation and Service Manual.
- (1) A421 Pilot's Warning Label.
- (1) Manufacturers Registration Card.
- (1) A438 Lens Masking Strip.
- (1) A445 Switch Label.
- (1) Warranty Certificate.
- (1) Aviation Catalog.
- (1) Trouble Shooting Procedure.
- (1) Aviation Price List.

©1998 Whelen Engineering Company. Form No.13295 (011298)

HS-5 Installation and Cable Package:

- (1) 5' 50635 Cable, One End with Sockets 61117-1 and (1) 1-480303-0 Connector Installed.
- (4) Pins 61118-1 and (1) 1-480305-0 Connector in Small Bag for Field Installation.
- (1) Installation and Service Manual.
- (1) A421 Pilot's Warning Label.
- (1) Manufacturers Registration Card.
- (1) A438 Lens Masking Strip.
- (1) A445 Switch Label.
- (1) Warranty Certificate.
- (1) Aviation Catalog.
- (1) Trouble Shooting Procedure.
- (1) Aviation Price List.

©1998 Whelen Engineering Company. Form No.13295 (011298)

HS-5 Installation and Cable Package:

- (1) 5' 50635 Cable, One End with Sockets 61117-1 and (1) 1-480303-0 Connector Installed.
- (4) Pins 61118-1 and (1) 1-480305-0 Connector in Small Bag for Field Installation.
- (1) Installation and Service Manual.
- (1) A421 Pilot's Warning Label.
- (1) Manufacturers Registration Card.
- (1) A438 Lens Masking Strip.
- (1) A445 Switch Label.
- (1) Warranty Certificate.
- (1) Aviation Catalog.
- (1) Trouble Shooting Procedure.
- (1) Aviation Price List.

©1998 Whelen Engineering Company. Form No.13295 (011298)

HS-5 Installation and Cable Package:

- (1) 5' 50635 Cable, One End with Sockets 61117-1 and (1) 1-480303-0 Connector Installed.
- (4) Pins 61118-1 and (1) 1-480305-0 Connector in Small Bag for Field Installation.
- (1) Installation and Service Manual.
- (1) A421 Pilot's Warning Label.
- (1) Manufacturers Registration Card.
- (1) A438 Lens Masking Strip.
- (1) A445 Switch Label.
- (1) Warranty Certificate.
- (1) Aviation Catalog.
- (1) Trouble Shooting Procedure.
- (1) Aviation Price List.

©1998 Whelen Engineering Company. Form No.13295 (011298)

HS-5 Installation and Cable Package:

- (1) 5' 50635 Cable, One End with Sockets 61117-1 and (1) 1-480303-0 Connector Installed.
- (4) Pins 61118-1 and (1) 1-480305-0 Connector in Small Bag for Field Installation.
- (1) Installation and Service Manual.
- (1) A421 Pilot's Warning Label.
- (1) Manufacturers Registration Card.
- (1) A438 Lens Masking Strip.
- (1) A445 Switch Label.
- (1) Warranty Certificate.
- (1) Aviation Catalog.
- (1) Trouble Shooting Procedure.
- (1) Aviation Price List.

©1998 Whelen Engineering Company. Form No.13295 (011298)

HS-5 Installation and Cable Package:

- (1) 5' 50635 Cable, One End with Sockets 61117-1 and (1) 1-480303-0 Connector Installed.
- (4) Pins 61118-1 and (1) 1-480305-0 Connector in Small Bag for Field Installation.
- (1) Installation and Service Manual.
- (1) A421 Pilot's Warning Label.
- (1) Manufacturers Registration Card.
- (1) A438 Lens Masking Strip.
- (1) A445 Switch Label.
- (1) Warranty Certificate.
- (1) Aviation Catalog.
- (1) Trouble Shooting Procedure.
- (1) Aviation Price List.

©1998 Whelen Engineering Company. Form No.13295 (011298)