





# WHELEN<sup>®</sup>

ENGINEERING COMPANY INC.

## Model 9E Lighthouse Waterproofing Kit

Route 145, Winthrop Road,  
Chester, Connecticut 06412  
Phone: (860) 526-9504  
Fax: (860) 526-4078

Internet: [www.whelen.com](http://www.whelen.com)  
Sales e-mail: [autosale@whelen.com](mailto:autosale@whelen.com)  
Canadian Sales e-mail: [autocan@whelen.com](mailto:autocan@whelen.com)  
Customer Service e-mail: [custserv@whelen.com](mailto:custserv@whelen.com)



**To Apply the Gasket:**

1. Prepare the surface of the lighthouse by cleaning any dirt or grease off with Isopropyl Alcohol (do not use rubbing alcohol as it contains oil).
2. Remove the tape covering the adhesive backing on the gasket. Apply the gasket as shown (Fig. 1), being sure to cover all 3 of the lens tab holes on the top of the lighthouse. You will have to mold the gasket into the top of the channel that runs around the lighthouse (Fig. 2).
3. This kit also contains a replacement reflector lens gasket. If your lighthouse does not have a foam in place gasket, you will need to replace this gasket also.

©2001 Whelen Engineering Company Inc.  
Form No.13653A (050302)





# WHELEN<sup>®</sup>

ENGINEERING COMPANY INC.

## Model 9E Lighthouse Waterproofing Kit

Route 145, Winthrop Road,  
Chester, Connecticut 06412  
Phone: (860) 526-9504  
Fax: (860) 526-4078

Internet: [www.whelen.com](http://www.whelen.com)  
Sales e-mail: [autosale@whelen.com](mailto:autosale@whelen.com)  
Canadian Sales e-mail: [autocan@whelen.com](mailto:autocan@whelen.com)  
Customer Service e-mail: [custserv@whelen.com](mailto:custserv@whelen.com)



**To Apply the Gasket:**

1. Prepare the surface of the lighthouse by cleaning any dirt or grease off with Isopropyl Alcohol (do not use rubbing alcohol as it contains oil).
2. Remove the tape covering the adhesive backing on the gasket. Apply the gasket as shown (Fig. 1), being sure to cover all 3 of the lens tab holes on the top of the lighthouse. You will have to mold the gasket into the top of the channel that runs around the lighthouse (Fig. 2).
3. This kit also contains a replacement reflector lens gasket. If your lighthouse does not have a foam in place gasket, you will need to replace this gasket also.

©2001 Whelen Engineering Company Inc.  
Form No.13653A (050302)