

SERVICE BULLETIN



C6, C7 and C9 SURFACEMAX™ SERIES

C Series Replacement gaskets are now available.

Part #:

C6 - 38-046H194-00 Revision A

C7 - 38-046H201-00 Revision A

C9 - 38046H179-00 Revision A

Replacement Gaskets: To obtain replacement gaskets, contact Whelen Technical Support at 860.526.9504, or email your request to custserv@whelen.com

If interim mounting method of applying RTV, as prescribed in Service Bulletin WSB002, was used there is no need to update to the new gasket. If the light head is removed for maintenance either remount with RTV or request a new gasket.

Distinguish OLD vs NEW:

