

WHELEN[®]

ENGINEERING COMPANY INC.

ROUTE 145, WINTHROP ROAD
CHESTER, CONNECTICUT 06412-0684
TELEPHONE: (860) 526-9504
FAX: (860) 526-4078


Whelen Preventive Maintenance Notification!

The linear flash tube that you returned for replacement shows signs that the tube has been exposed to high energy arcing. When this condition exists, damage to the tube's contact points and the reflector clips will occur. This type of damage cannot be repaired by the owner and furthermore, will damage any new flash tubes that are installed.

Carefully inspect the reflector clips for ANY indication that arcing has occurred. This is usually represented by small, "scorched" or pitted areas on the clip surface that holds the flash tube in place. If these marks are evident, the reflector must be returned to the factory and replaced.

For "Warranty Claims", return damaged items directly to the factory. See attached warranty statement.

For equipment that is no longer covered by warranty, contact your nearest Whelen distributor for replacements.



©1996 Whelen Engineering Company.
Form No.13109 (031596)

WHELEN[®]

ENGINEERING COMPANY INC.

ROUTE 145, WINTHROP ROAD
CHESTER, CONNECTICUT 06412-0684
TELEPHONE: (860) 526-9504
FAX: (860) 526-4078


Whelen Preventive Maintenance Notification!

The linear flash tube that you returned for replacement shows signs that the tube has been exposed to high energy arcing. When this condition exists, damage to the tube's contact points and the reflector clips will occur. This type of damage cannot be repaired by the owner and furthermore, will damage any new flash tubes that are installed.

Carefully inspect the reflector clips for ANY indication that arcing has occurred. This is usually represented by small, "scorched" or pitted areas on the clip surface that holds the flash tube in place. If these marks are evident, the reflector must be returned to the factory and replaced.

For "Warranty Claims", return damaged items directly to the factory. See attached warranty statement.

For equipment that is no longer covered by warranty, contact your nearest Whelen distributor for replacements.



©1996 Whelen Engineering Company.
Form No.13109 (031596)